

Hydes4606

4606 Hixson Pike
Hixson, TN 37343
(423) 825-4933
hydes4606@yahoo.com
<http://takeittohydes.com>

RO #3979

Service Advisor: MICHAEL STAYMAN
Posted Date: 06/16/26 at 04:37 PM EDT
Client: Adam Delrosso
Vehicle: 2019 Subaru Outback 2.5i Limited

2019 Subaru Outback 2.5i Limited 2.5L 4Cyl GAS FB25 Naturally Aspirated
VIN: N/A
License: N/A
Color: N/A
Odometer In: 98304 / Out: 98304

RO # 3979
Save Parts: No

Client Concerns

PRE SALE INSPECTION

Inspection Rating Key:

☺ Checked & Okay ⚠ Requires Attention Soon ✖ Requires Immediate Attention — Not Applicable

20 Point Inspection

TECH: Shane Morrison

☺ ⚠ ✖ — 20 Point Inspection

☒ ☐ ☐ ☐ Test Drive	Finding:
☒ ☐ ☐ ☐ Horn	Finding:
☒ ☐ ☐ ☐ Belts and Hoses	Finding:
☐ ☒ ☐ ☐ Engine Oil & Fluids	Finding: Engine oil about a half quart low
☒ ☐ ☐ ☐ Brakes Visual	Finding: Front pads 8mm, Rear pads 5mm
☒ ☐ ☐ ☐ Cooling System	Finding:
☒ ☐ ☐ ☐ Wiper Blades	Finding:
☒ ☐ ☐ ☐ Air Filters 	Finding:
☒ ☐ ☐ ☐ Alignment	Finding:
☒ ☐ ☐ ☐ Exhaust	Finding:
☒ ☐ ☐ ☐ Axle Boots	Finding:
☐ ☒ ☐ ☐ Steering	Finding:
☐ ☒ ☐ ☐ Suspension 	Finding: Left front strut has seepage starting
☒ ☐ ☐ ☐ Body Inspection	Finding:

☒ ☐ ☐ ☐ Transmission	Finding:
☐ ☐ ☒ ☐ Tire Pressure 	Finding: TPMS light on, no output from LF sensor, RF sensor has a low battery level , tire treads are getting low (3mm all)
☒ ☐ ☐ ☐ Battery (If Accessible) 	Finding:
☒ ☐ ☐ ☐ Ignition System	Finding:
☒ ☐ ☐ ☐ Exterior / Interior Bulbs	Finding:
☐ ☐ ☒ ☐ Dash Lights	Finding: TPMS light on